

CW-113 Adjustable Decline Bench Pivot Bolt Replacement

Applies to

Icarian CW-113 Adjustable Decline Bench

Issue/Symptoms

The back support to main frame pivot connection may become loose. The pivot bolt torque specification was not large enough to keep the connection tight during extended use.

Resolution

Replace the existing button head bolt with a new socket head bolt allowing increased torque capacity (75 ft-lbs (102 Nm)).



CW-113 Adjustable Decline Bench

Tools Required

- 3/8" Hex Key Wrench
- M8 Hex Key Wrench
- M10 Hex Key Wrench
- 3/4 in socket.
- Torque wrench, 75 ft-lb (100 nm) range

Parts required

QTY	Part Number	Description
1	PPP00000CW58119101*	CS KIT, CW-113 PIVOT BOLT UPGRADE

Note: * Kit includes required replacement parts.

Procedure

Follow the installation instructions included with the kit PPP00000CW58119101.